



VOLKSWAGEN Touran: 1HY509			
Vinnnumber:	WVGZZZ1TZFW026792	Versionname:	TOURAN Trendline BMT St/St 7pl/DSG 105PK
First Registrationdate:	3/11/2014	Fiscalpower:	
Expertise Mileage:	93793	Power Kw:	77
Bodytype:	MPV	Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4624
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment	
Total cost ex VAT	618,98
Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Stone chip(s), Windscreen repair	58,80

	Interior, Dirty, Cleaning	0,00
--	---------------------------	------



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00

