



## VOLKSWAGEN Touran: 1FAN353

Vinnnumber:	<b>WVGZZZ1TZDW101575</b>	Versionname:	<b>TOURAN Trendline BMT</b>
First Registrationdate:	<b>7/05/2013</b>	Fiscalpower:	<b>Start/Stop 105PK</b>
Expertise Mileage:	<b>146805</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4414</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

## Options

Radio CD		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Type of headlighting	<b>Headlighting Halogen</b>	Type of Tow bar	<b>Tow bar removable</b>
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/55/16/91 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 8 mm</b>	Fr.R.	<b>Continental: 8 mm</b>
	Re.L.	<b>Kleber: 7 mm</b>	Re.R.	<b>Kleber: 7 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	815,15
-------------------	--------

Interior, Dirty, Cleaning	0,00
---------------------------	------



Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	------


No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------





Rear window, Scratch(es), E - Replace 0,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35

