



## VOLKSWAGEN Golf: 1FU0331

Vinnnumber:	<b>WVWZZZAUZEP533320</b>	Versionname:	<b>GOLF VAR Trendline DSG</b>
First Registrationdate:	<b>29/10/2013</b>	Fiscalpower:	<b>105PK Aut.</b>
Expertise Mileage:	<b>119023</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4302</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD	Sun Roof electric	
Windows electric F	Panoramic roof	
Windows electric R	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunctional	Front parking sensors	
Seats F heated	Rear parking sensors	
Radio multimedia	Type of Tow bar	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>195/65/15/91 T Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	228,60
Wheel cover F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Bump(s), PDR - Knock out without painting	63,00



Bumper corner R L, Scratch(es), Acceptable	0,00
--------------------------------------------	------

*No pictures to display*

Door F L, Bump(s), PDR - Knock out without painting	63,00
-----------------------------------------------------	-------



Wing R L, Bump(s), PDR - Knock out without painting	102,60
-----------------------------------------------------	--------

