


**AUDI A4: 1FCY717**

Vinnumber:	<b>WAUZZZ8K6DA226869</b>	Versionname:	<b>A4 AVANT TDi Multitr.136PK Aut.</b>
First Registrationdate:	<b>28/05/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>185870</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1115</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>25/55/16/95 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Uniroyal: 3 mm</b>	Fr.R.	<b>Uniroyal: 3 mm</b>
	Re.L.	<b>Uniroyal: 4 mm</b>	Re.R.	<b>Uniroyal: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	1036,35
Ignition key, Missing, E - Replace	150,00

*No pictures to display*

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Sill outer R, Accident, LI - Repair and paint (complete)	0,00
--	------



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Damaged, Le - Replace and paint 0,00



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Door F R, Accident, Le - Replace and paint 0,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s), LI - Repair and paint (complete) 259,80



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20

