



BMW 1 HATCH: 1NJF797

Vinnumber:	WBA1C91070P875868	Versionname:	1.6 116D EFFICIENTDYNAMICS EDIT. (85KW)
First Registrationdate:	17/02/2015	Fiscalpower:	
Expertise Mileage:	125689	Power Kw:	85
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3523
Maintenance:	OVER 2800KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	858,60
-------------------	---------------

Alloy rim F R, Scratch(es), Acceptable	0,00
--	-------------



Tires, Out of tolerance, P - Check	0,00
------------------------------------	-------------



Wing R R, Bump(s), Acceptable 0,00



Rearlight L, Damaged, E - Replace 114,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Interior, Dirty, Cleaning 25,00



Seat cover F L, Worn, Acceptable 0,00



Foglight L, Damaged, E - Replace 138,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Windscreen, Repaired, Acceptable 0,00



Door R R, Bump(s), PDR - Knock out without painting 63,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

