


**AUDI A3: 1FFW113**

Vinnnumber:	<b>WAUZZZ8V8EA005625</b>	Versionname:	<b>A3 SB Ambiente 105PK</b>
First Registrationdate:	<b>18/06/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>148886</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance	<b>9100</b>	Parking lot:	<b>3611</b>
Maintenance	<b>OK</b>		
Maintenance	<b>279 DAGEN</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>SD</b>	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar removable</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>1428,76</b>
-------------------	----------------

Sill trim R R, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>342,35</b>
---	---------------





Internal Boot Lining R, Damaged, Acceptable 0,00

No pictures to display

Ignition key, Not functioning (well), Repair/replace (lump sum) 0,00



Outer backrest protection R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bad repair, Acceptable 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 235,80



Glove compartment lid, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Outer backrest protection L, Scratch(es), E - Replace 139,70



Sill trim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Bump(s) and scratch(es), It - Spot repair	115,56



Internal Boot Lining L, Dirty, Acceptable	0,00
<i>No pictures to display</i>	
Door panel F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door frame R L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Rearview mirror housing L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear bulkhead lining, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Ceiling, Dirty, Acceptable 0,00

No pictures to display

Bumper R, Repaired, Acceptable 0,00



Sill trim F R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Scratch(es), Acceptable 0,00

No pictures to display

Sill trim R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s), PDR - Knock out without painting 63,00



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 342,35



Seat F L compl, Worn, Acceptable 0,00

