


AUDI A4: 1GWN855

Vinnumber:	WAUZZZ8KXE154785	Versionname:	A4 AVANT TDie 136PK
First Registrationdate:	20/05/2014	Fiscalpower:	
Expertise Mileage:	170418	Power Kw:	100
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4601
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	CD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Firestone: 3 mm	Fr.R.	Firestone: 3 mm
	Re.L.	Michelin: 2,6 mm	Re.R.	Michelin: 2,6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 1372,30

Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80





Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Sill trim R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Door R R, Bump(s), PDR - Knock out without painting 159,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Seat cover F L, Stain, Acceptable 0,00

No pictures to display