


AUDI A3: 1GNJ708

| | | | |
|------------------------------------|-------------------------|--------------|-----------------------------|
| Vinnnumber: | WAUZZZ8VXE154327 | Versionname: | A3 SB Ambiente 105PK |
| First Registrationdate: | 18/03/2014 | Fiscalpower: | |
| Expertise Mileage: | 80436 | Power Kw: | 77 |
| Bodytype: | | Body color: | White |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 4307 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|-----------------------|
| Radio CD | | Central consol F |
| GPS storage | HD | Luggage cover |
| GPS storage | | Front parking sensors |
| Windows electric F | | Rear parking sensors |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 205/55/16/98 H LightMetal | | | |
| Summer tyres: | Fr.L. | Continental: 4 mm | Fr.R. | Continental: 4 mm |
| | Re.L. | Continental: 4 mm | Re.R. | Continental: 4 mm |

Assistance equipment

| | |
|---------|-----------|
| Runflat | No |
|---------|-----------|

| | |
|--|---------------|
| Total cost ex VAT | 119,00 |
| Front bumper, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |



| | |
|---------------------------------|-------|
| Seat cover R R, Stain, Cleaning | 12,00 |
|---------------------------------|-------|



| | |
|---------------------------------|-------|
| Seat cover F R, Stain, Cleaning | 12,00 |
|---------------------------------|-------|



| | |
|---|------|
| Rear Panel Internal Lining, Scratch(es), Acceptable | 0,00 |
|---|------|

No pictures to display