


**AUDI A6: 1EUJ449**

|                         |                          |              |                     |
|-------------------------|--------------------------|--------------|---------------------|
| Vinnumber:              | <b>WAUZZZ4G1DN102549</b> | Versionname: | <b>A6 BER 136PK</b> |
| First Registrationdate: | <b>22/03/2013</b>        | Fiscalpower: |                     |
| Expertise Mileage:      | <b>161382</b>            | Power Kw:    | <b>100</b>          |
| Bodytype:               |                          | Body color:  | <b>Brown</b>        |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>      |
| Transmission:           | <b>Front</b>             | Rims summer: | <b>Aluminium</b>    |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>           |
| Maintenance:            | <b>OK</b>                | Parking lot: | <b>1122</b>         |
| Battery functioning:    | <b>Yes</b>               |              |                     |
| Number of doors:        | <b>4</b>                 |              |                     |
| Number of seats:        | <b>5</b>                 |              |                     |
| Number head rests:      | <b>5</b>                 |              |                     |
| Rims summer:            | <b>Aluminium</b>         |              |                     |
| Category:               | <b>Passenger Car</b>     |              |                     |
| Oil level:              | <b>OK</b>                |              |                     |

**Options**

|                                |                              |                       |
|--------------------------------|------------------------------|-----------------------|
| Radio CD                       |                              | Central consol F      |
| GPS storage                    |                              | Luggage cover         |
| GPS storage                    | <b>SD</b>                    | Front parking sensors |
| Windows electric F             |                              | Rear parking sensors  |
| Windows electric R             |                              |                       |
| Cruise Control                 |                              |                       |
| Steering wheel multifunctional |                              |                       |
| Seats F heated                 |                              |                       |
| Radio multimedia               |                              |                       |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                       |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |
| Type of Lining                 | <b>Lining leather</b>        |                       |
| Type of climate control        | <b>Autom climate control</b> |                       |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>225/60/16/98 W LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Michelin: 5 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|               | Re.L.                            | <b>Michelin: 5 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

**Assistance equipment**

|  |            |            |              |
|--|------------|------------|--------------|
| Repair kit                             | <b>Yes</b> | Compressor | <b>Yes</b>   |
| Total cost ex VAT                      |            |            | <b>95,00</b> |
| Alloy rim R R, Scratch(es), Acceptable |            |            | <b>0,00</b>  |
| <i>No pictures to display</i>          |            |            |              |
| Door F L, Scratch(es), Acceptable      |            |            | <b>0,00</b>  |
| <i>No pictures to display</i>          |            |            |              |
| Wing R L, Scratch(es), Acceptable      |            |            | <b>0,00</b>  |
| <i>No pictures to display</i>          |            |            |              |
| Bumper R, Scratch(es), Acceptable      |            |            | <b>0,00</b>  |
| <i>No pictures to display</i>          |            |            |              |
| Wing R R, Bad repair, Paint            |            |            | <b>0,00</b>  |



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Rearview mirror housing R, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim F R, Scratch(es), Acceptable 0,00

*No pictures to display*