



BMW 2 GRAN TOURER: 90490

Vinnumber:	WBA2E510805C10130	Versionname:	2.0 218D (110KW) GRAN TOURER
First Registrationdate:	30/07/2015	Fiscalpower:	
Expertise Mileage:	64347	Power Kw:	110
Bodytype:		Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2713
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Sun Roof electric
GPS storage	HD	Panoramic roof
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/91 H LightMetal			
Summer tyres:	Fr.L.	Hankook: 3 mm	Fr.R.	Hankook: 3 mm
	Re.L.	Hankook: 4 mm	Re.R.	Hankook: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	564,88
-------------------	---------------

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Door R R, Bad repair, Acceptable	0,00
----------------------------------	-------------



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Roof, Bump(s), PDR - Knock out without painting	63,00
---	-------



Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

