



BMW X4: CN6645

Vinnnumber:	WBAXX110900R39174	Versionname:	2.0 XDRIVE20D (140KW)
First Registrationdate:	24/11/2015	Fiscalpower:	4WD
Expertise Mileage:	37805	Power Kw:	140
Bodytype:		Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2626
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/50/18/100 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	1316,03
Door R R, Bump(s), PDR - Knock out without painting	82,80





Windscreen, Stone chip(s), Windscreen repair 58,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Air vent R M, Damaged, E - Replace 158,40



Roof, Chemical polution, 67 - Polish 55,19



Door F L, Bump(s) and scratch(es), Acceptable 0,00



Wing trim R R, Scratch(es), Smart repair 110,64



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R L, Scratch(es), Acceptable 0,00

No pictures to display

Door moulding Lower F R, Scratch(es), Smart repair 110,64



Sill outer R, Scratch(es), It - Spot repair 115,56



Seat cover R R, Deformed, Acceptable	0,00
--------------------------------------	------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R R, Bump(s), LI - Repair and paint (complete)	369,84
---	--------



Rocker panel inner R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display