



**BMW 4: 1GUR671**

Vinnumber:	<b>WBA3U11010J877710</b>	Versionname:	<b>4 CABRIO 420d 163PK</b>
First Registrationdate:	<b>6/05/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>82132</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4232</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>2</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Sun Roof electric
GPS storage	Rear parking sensors
GPS storage <b>HD</b>	Type of Tow bar <b>Tow bar fixed</b>
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting <b>Headlighting Xenon</b>	
Type of GPS <b>GPS big screen color</b>	
Type of Lining <b>Lining leather</b>	
Type of climate control <b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/50/17/92 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 5 mm</b>	Fr.R.	<b>Goodyear: 5 mm</b>
	Re.L.	<b>Goodyear: 5 mm</b>	Re.R.	<b>Goodyear: 5 mm</b>

**Assistance equipment**

Total cost ex VAT	2024,82
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	369,84



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Windscreen, Stone chip(s), Windscreen repair 0,00



Tailgate, Bad repair, Acceptable 0,00



Front bumper, Bump(s), Le - Replace and paint 862,80



Door F R, Scratch(es), LI - Repair and paint (complete) 382,02



Foglight R, Damaged, E - Replace 156,00

