


BMW 3: 1GHS466

Vinnumber:	WBA3Y11050D448122	Versionname:	3 GRAN TURISMO 318d
First Registrationdate:	11/02/2014	Fiscalpower:	136PK
Expertise Mileage:	112282	Power Kw:	100
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1716
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	0,00
Door R L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Repaired, P - Check	0,00



Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Repaired, P - Check	0,00

