


CITROEN C4 Picasso: 1GWX962

Vinnumber:	VF73A9HC8EJ642407	Versionname:	GR.C4 PICASSO Intensive
First Registrationdate:	22/05/2014	Fiscalpower:	115PK
Expertise Mileage:	149915	Power Kw:	85
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2730
Battery functioning	Yes		
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage		Seats electric F L
GPS storage	HD	Seats electric F R
Windows electric F		Panoramic roof
Windows electric R		Central consol F
Cruise Control		Luggage cover
Steering wheel multifunction		Rear parking sensors
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/95 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2094,58
-------------------	---------

Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68
---	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Rear bulkhead lining, Strained , P - Check 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display


Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Protection plate M, Hole, E - Replace 35,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 366,35

