



**BMW 5 TOURING: 1KAP906**

Vinnnumber:	<b>WBA5L11060D969194</b>	Versionname:	<b>2.0 518D (100KW) TOURING</b>
First Registrationdate:	<b>19/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>116952</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3533</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar removable</b>
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>245/45/18/100 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Dunlop: 4 mm</b>	Fr.R.	<b>Dunlop: 4 mm</b>
	Re.L.	<b>Dunlop: 4 mm</b>	Re.R.	<b>Dunlop: 4 mm</b>

**Assistance equipment**

Runflat	<b>Yes</b>
---------	------------

Total cost ex VAT	<b>1933,62</b>
-------------------	----------------

Door F R, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------


*No pictures to display*

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
---	--------------





Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 406,02



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 369,84



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 326,16





Backrest cover F L, Worn, Acceptable	0,00
--------------------------------------	------



Alloy rim F R polished, Damaged, E - Replace	277,44
--	--------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

*No pictures to display*

Alloy rim F R polished, Missing, E - Replace	15,00
--	-------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*