



IVECO Daily 40C15: 1BSY980

Vinnumber:	ZCFC40A4205883427	Versionname:	DAILY CH2C 40C15 146PK
First Registrationdate:	25/08/2011	Fiscalpower:	3500KG
Expertise Mileage:	212098	Power Kw:	107
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV28
Number of doors:	4		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	

Limited Technical Inspection

Tires wear profile	OK	Battery functioning	Yes
Idle position	OK	Power steering	Yes
Engine startingtime	OK	Sound engine	OK
Exhaust gass	OK	Clutch test	NOT OK
Handbrake	OK	Wiper fluid level	OK
		Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/75/16/105 R Steel			
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 3376,26

Engine, Not functioning (well), Diagnosis 0,00



Interior, Stain, Cleaning 200,00



Armrest L, Strained , Repair/replace (lump sum) 29,00



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Bagage rack, Damaged, Acceptable 0,00



Front bumper, Bump(s) and scratch(es), Le - Replace and paint 575,25



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Roof, Chemical polution, LI - Repair and paint (complete) 361,13










Dashboard, Hole, Smart repair 110,64



Tyre R L, No damage, Acceptable 0,00



Windscreen Broken, E - Replace 395,40

Windscreen, Broken, E - Replace		350,00
		
Sill outer L, Scratch(es), LI - Repair and paint (complete)		232,88
		
Rearview mirror L complete, Scratch(es), Acceptable		0,00
No pictures to display		
Seat cover F R, Burned, Smart repair		64,32
		
Ignition key, Missing, E - Replace		150,00
		
Wheel cover F R, Scratch(es), Acceptable		0,00
No pictures to display		
Seat cover F L, Tear, E - Replace		300,00
		
Grill, Broken, E - Replace		99,00
		
Door frame F R, Bump(s) and scratch(es), It - Spot repair		115,56
		
Rearview mirror R complete, Scratch(es), Acceptable		0,00
No pictures to display		
Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)		265,56

