




MERCEDES A: 1JHE099			
Vinnumber:	<b>WDD1760121V047572</b>	Versionname:	<b>A 180CDI BE Edition 109PK</b>
First Registrationdate:	<b>18/12/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>79449</b>	Power Kw:	<b>80</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3428</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Central consol F
GPS storage	HD Luggage cover
GPS storage	Rear parking sensors
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>195/65/15/91 T Steel</b>			
Summer tyres:	Fr.L.	<b>Dunlop: 4 mm</b>	Fr.R.	<b>Dunlop: 4 mm</b>
	Re.L.	<b>Dunlop: 3 mm</b>	Re.R.	<b>Dunlop: 3 mm</b>



Assistance equipment			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>115,00</b>
Rear window, Scratch(es), E - Replace			<b>0,00</b>



Seat cover F R, Stain, Cleaning	<b>25,00</b>
---------------------------------	--------------



Bodywork, Repaired, Acceptable 0,00



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Wheel cover F L, Scratch(es), E - Replace 30,00



Bonnet, Repaired, Acceptable 0,00

No pictures to display

Window R L door, Scratch(es), E - Replace 0,00

