


**LU Skoda Superb: DY7163**

Vinnnumber:	<b>TMBAH9NP0H7502159</b>	Versionname:	<b>2.0 TDI 110KW STYLE DSG</b>
First Registrationdate:	<b>9/09/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>30613</b>	Power Kw:	<b>110</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>2724</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats R heated
GPS storage	<b>HD</b>	Seats electric F L
GPS storage		Seats electric F R
Windows electric F		Sun Roof electric
Windows electric R		Central consol F
Cruise Control		Luggage cover
Steering wheel multifunctional		Front parking sensors
Seats F heated		Rear parking sensors
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>235/45/18/94 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Hankook: 7 mm</b>	Fr.R.	<b>Hankook: 7 mm</b>
	Re.L.	<b>Hankook: 7 mm</b>	Re.R.	<b>Hankook: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>460,16</b>
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			<b>95,00</b>



Front bumper, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), Acceptable	<b>0,00</b>



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	302,16
---	--------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Tailgate, Bump(s), PDR - Knock out without painting	63,00
---	-------



Door F R, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Maintenance, Maintenance, Execute	0,00
-----------------------------------	------

*No pictures to display*