



<b>FORD Mondeo: 1E2P815</b>			
Vinnnumber:	<b>WFOEXXGBBEM09877</b>	Versionname:	<b>MONDEO BER Econetic Titanium 115PK</b>
First Registrationdate:	<b>30/04/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>113532</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1328</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>215/55/16/97 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Firestone: 4 mm</b>	Fr.R.	<b>Firestone: 4 mm</b>
	Re.L.	<b>Firestone: 5 mm</b>	Re.R.	<b>Firestone: 5 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>290,08</b>
Door F R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)			<b>290,08</b>



Bumper B, Scratch(es), Acceptable			<b>0,00</b>
-----------------------------------	--	--	-------------

Bumper R, scratches, Acceptable	0,00
<i>No pictures to display</i>	
Sill outer R, Bad repair, Acceptable	0,00

