



MERCEDES A: 1GSG450

Vinnumber:	WDD1760121V014042	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	15/04/2014	Fiscalpower:	
Expertise Mileage:	74683	Power Kw:	80
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	A DANS 22600 KM	Parking lot:	2405
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/40/18/92 Y LightMetal			
Summer tyres:	Fr.L.	Semperit: 9 mm	Fr.R.	Semperit: 9 mm
	Re.L.	Semperit: 9 mm	Re.R.	Semperit: 9 mm

Assistance equipment

Repair kit	No	Compressor	Yes
------------	-----------	------------	------------

Total cost ex VAT	917,89
-------------------	---------------

Bumper F R, Scratch(es), It - Spot repair	115,56
-------------------------------------------	---------------



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
-----------------------------------------------------------------------	--------------



Rocker panel inner F R, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Tyre repair kit, Empty, E - Replace 210,53



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00

