



| MERCEDES B: 1EUJ480 | | | |
|-------------------------|--------------------------|--------------|---------------------------|
| Vinnumber: | WDD2462011J145366 | Versionname: | B 200 CDI BE 136PK |
| First Registrationdate: | 22/03/2013 | Fiscalpower: | |
| Expertise Mileage: | 60896 | Power Kw: | 100 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 2812 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

| Options | |
|--|-----------------------|
| Radio CD | Sun Roof electric |
| GPS storage HD | Panoramic roof |
| GPS storage | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Steering wheel multifunctional | Rear parking sensors |
| Seats F heated | |
| Type of headlighting Headlighting Halogen | |
| Type of GPS GPS big screen color | |
| Type of Lining Lining leather | |
| Type of climate control Autom climate control | |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| Degree of wear | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 225/45/17/91 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Continental: 3 mm | Fr.R. | Continental: 3 mm |
| | Re.L. | Continental: 4 mm | Re.R. | Continental: 4 mm |

| Assistance equipment | | | |
|-------------------------------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 2046,83 |
| Alloy rim F L, Damaged, E - Replace | | | 235,20 |



| | |
|--|-------|
| Windscreen, Stone chip(s), Windscreen repair | 58,80 |
|--|-------|



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Sill outer L, Scratch(es), LI - Repair and paint (complete) 310,50



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Alloy rim F R, Damaged, E - Replace 235,20



Ignition key, Missing, E - Replace 150,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

