



FORD Galaxy: 1GIQ644

Vinnnumber:	WF0MXXGBWMEY20591	Versionname:	GALAXY Titanium Style DPF 136PK
First Registrationdate:	18/02/2014	Fiscalpower:	
Expertise Mileage:	154042	Power Kw:	100
Bodytype:	MPV	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3722
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Central consol F	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar fixed
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	0,00
-------------------	-------------

Door R R, Scratch(es), LI - Repair and paint (complete)	0,00
---	-------------






Door R L, Bump(s), Acceptable 0,00

No pictures to display

Roof pillar R, Scratch(es), LI - Repair and paint (complete) 0,00



Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Bumper corner R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display


Wing R R, Scratch(es), LI - Repair and paint (complete) 0,00



Luggage space cover, Missing, E - Replace 0,00



Roof, Chemical pollution, LI - Repair and paint (complete) 0,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 0,00



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Bonnet, Scratch(es), LI - Repair and paint (complete) 0,00



Interior, Dirty, Cleaning 0,00

