



**OPEL Astra: 1HJH687**

Vinnumber:	<b>WOLPE8E60E8071220</b>	Versionname:	<b>ASTRA BRE ecoFLEX Cosmo St/St 110PK</b>
First Registrationdate:	<b>1/08/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>175528</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2304</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Sun Roof electric
GPS storage	Central consol F
GPS storage <b>HD</b>	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Alarm	
Type of headlighting <b>Headlighting LED</b>	
Type of GPS <b>GPS big screen color</b>	
Type of Lining <b>Lining leather</b>	
Type of climate control <b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/50/17/94 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Kleber: 7 mm</b>	Re.R.	<b>Kleber: 7 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>231,12</b>
Door R R, Bump(s) and scratch(es), It - Spot repair	<b>115,56</b>



Front bumper, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Door F L, Bad repair, Paint	<b>0,00</b>



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door frame F L, Bump(s) and scratch(es), It - Spot repair 115,56



Wing F L, Bad repair, Paint 0,00



Door R L, Bad repair, Paint 0,00

