



PEUGEOT 5008: 1FTP470

Vinnnumber:	VF30E9HD8DS179970	Versionname:	5008 e-HDi Allure FAP BMP 115PK Aut.
First Registrationdate:	21/10/2013	Fiscalpower:	
Expertise Mileage:	73731	Power Kw:	84
Bodytype:	MPV	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2619
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Panoramic roof
GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		Night vision
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Head-up Display		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/97 H LightMetal			
Summer tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2275,01
Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	301,68





Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Hail damage, LI - Repair and paint (complete) 481,50



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), E - Replace 235,20



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wheel arch cover F R, Broken, E - Replace 78,92



Tailgate, Hail damage, PDR - Hail 25,00



Wing R R, Scratch(es), 67 - Polish 55,19



Door R R, Scratch(es), 67 - Polish 55,19



Wing F R, Scratch(es), 67 - Polish 55,19



Door F R, Scratch(es), 67 - Polish 55,19



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display