


MINI Mini COOPER D: 1ESM057

Vinnnumber:	WMWSW31090T232163	Versionname:	MINI Cooper D 112PK DPF
First Registrationdate:	8/03/2013	Fiscalpower:	
Expertise Mileage:	158861	Power Kw:	82
Bodytype:		Body color:	Orange
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2608
Maintenance:	IN 28000 KM		
Battery functioning:	Yes		
Number of doors:	3		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	175/65/15/84 H LightMetal			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 2 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
		Jack	Yes

Total cost ex VAT	1065,43
-------------------	---------

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------



Bumper R, Scratch(es), Acceptable 0,00



Wing R L, Scratch(es), Acceptable 0,00



Wing R R, Bump(s), Acceptable 0,00



Windscreen, Stone chip(s), Windscreen repair 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 342,35



Bumper spoiler F, Scratch(es), E - Replace 42,00



Foglight R, Stone chip(s), E - Replace 138,00



Wing R L, Bump(s), PDR - Knock out without painting 63,00



Front bumper, Stone chip(s), Acceptable 0,00



Wing moulding F L, Scratch(es), Acceptable 0,00



Bonnet, Stone chip(s), LI - Repair and paint (complete) 290,08



Door F L, Bump(s) and scratch(es), Acceptable 0,00



Roof, Stone chip(s), Acceptable 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

