


MERCEDES E BERLINE: 1JXJ952

Vinnnumber:	WDD2120981A909438	Versionname:	2.1 E 300 BLUETEC HYBRID AUTO AVANTGARDE
First Registrationdate:	12/03/2015	Fiscalpower:	
Expertise Mileage:	129723	Power Kw:	170
Bodytype:	Berline	Body color	Dark Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Hybrid Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1714
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/17/99 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 3 mm	Re.R.	Pirelli: 3 mm

Assistance equipment










Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1539,26

Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16

Alloy rim R R polished, Scratch(es), Acceptable

0,00

<i>No pictures to display</i>		
Bonnet, Chemical polution, LI - Repair and paint (complete)		348,09
		
Roof, Chemical polution, LI - Repair and paint (complete)		577,80
		
Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)		264,21
		
		
Wing R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)		95,00
