



MITSUBISHI Outlander: 1FBP094

Vinnumber:	JMBXJGF6WDZ406276	Versionname:	OUTLANDER 2WD Intense
First Registrationdate:	16/05/2013	Fiscalpower:	150PK
Expertise Mileage:	202666	Power Kw:	110
Bodytype:		Body color:	Orange
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1315
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/70/16/100 T LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	178,56
-------------------	---------------

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	-------------

No pictures to display


Door R L, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing R L, Bump(s), PDR - Knock out without painting	63,00
---	--------------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

<i>No pictures to display</i>		
Bumper corner R R, Scratch(es), It - Spot repair		115,56
		
Wing F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		