



OPEL Insignia: 1FEH488

Vinnumber:	WOLGM8EJ6D1110374	Versionname:	INSIGNIA BRE ecoFL.Edition DPF 110PK
First Registrationdate:	6/06/2013	Fiscalpower:	
Expertise Mileage:	174853	Power Kw:	81
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2203
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	NOT OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 V LightMetal			
Summer tyres:	Fr.L.	Firestone: 4 mm	Fr.R.	Firestone: 4 mm
	Re.L.	Firestone: 5 mm	Re.R.	Firestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	0,00
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Chemical polution, Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Bad repair, Acceptable	0,00



Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy Rims (all), Rust, Acceptable	0,00

