


PEUGEOT 308: 1HCY538

Vinnnumber:	VF3LC9HPAES140184	Versionname:	308 SW Active 92PK
First Registrationdate:	20/06/2014	Fiscalpower:	
Expertise Mileage:	106545	Power Kw:	68
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2212
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Panoramic roof
GPS storage	HD	Central consol F
Windows electric F		Luggage cover
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 551,80

Door F R, Scratch(es), Acceptable 0,00

No pictures to display
Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display
Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

No pictures to display
Ignition key, Missing, F - Replace 150,00



Wing R L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display