


OPEL Zafira: 1FEY434

Vinnumber:	W0LPE9EM7D2060771	Versionname:	ZAFIRA TOURER
First Registrationdate:	11/06/2013	Fiscalpower:	ecoFL.Cosmo St/St.130PK
Expertise Mileage:	83905	Power Kw:	96
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2123
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/94 V LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

 Total cost ex VAT 848,37

 Maintenance book, Missing, E - Replace 0,00

No pictures to display

 Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



 Door R L, Scratch(es), Acceptable 0,00

No pictures to display

 Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

 Door R R, Scratch(es), Acceptable 0,00

<i>No pictures to display</i>		
Seat cover F L, Worn, Acceptable		0,00
		
<i>No pictures to display</i>		
Wing R L, Scratch(es), Acceptable		0,00
		
Wing F R, Accident, Le - Replace and paint		530,02