



<b>NISSAN Qashqai: 1HBK094</b>			
Vinnnumber:	<b>SJNFEAJ10U2930410</b>	Versionname:	<b>QASHQAI 2WD 360 ISS</b>
First Registrationdate:	<b>11/06/2014</b>	Fiscalpower:	<b>130PK</b>
Expertise Mileage:	<b>106216</b>	Power Kw:	<b>96</b>
Bodytype:	<b>SUV</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2613</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>	
Radio CD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-artificial leather</b>
Type of climate control	<b>Autom climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>215/55/18/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>1096,17</b>
Door F L, Bump(s) and scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Roof, Bump(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)			<b>318,35</b>



Alloy rim F R polished, Damaged, E - Replace	<b>235,20</b>
--	---------------



Rearview mirror housing L, Scratch(es), Smart repair 110,64



Door R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim R R polished, Rust, Acceptable 0,00

*No pictures to display*

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F R, Bump(s), LI - Repair and paint (complete) 220,18

