



OPEL VIVARO: 1LFT579

Vinnnumber:	W0L3F7018GS017175	Versionname:	1.6CDTI 85KW EDITION LWB 2.9T
First Registrationdate:	16/09/2015	Fiscalpower:	
Expertise Mileage:	160583	Power Kw:	85
Bodytype:	Transporter	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4221
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics

Limited Technical Inspection

Tires wear profile	OK	Battery functioning	Yes
Idle position	OK	Power steering	Yes
Engine startingtime	OK	Sound engine	OK
Exhaust gass	OK	Clutch test	OK
Handbrake	OK	Wiper fluid level	OK
		Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/105 T Steel			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------


Total cost ex VAT	662,89
Door F L, Scratch(es), LI - Repair and paint (complete)	238,76



Trunk door R L, Bump(s), PDR - Knock out without painting	63,00
---	--------------



Roof, Bump(s), LI - Repair and paint (complete)	361,13
---	---------------



Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	