


OPEL Insignia: 1GQV615

Vinnnumber:	WOLGT6ER5E1103849	Versionname:	INSIGNIA BER ecoFLEX Cosmo 120PK
First Registrationdate:	3/04/2014	Fiscalpower:	
Expertise Mileage:	133971	Power Kw:	88
Bodytype:		Body color:	Green
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2312
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2155,93
-------------------	---------

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)	310,50
---	--------




Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Bad repair, LI - Repair and paint (complete) 318,35



Bonnet, Bump(s), Acceptable 0,00

No pictures to display

Engine protective plate, Tear, E - Replace 89,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Bad repair, LI - Repair and paint (complete) 301,68



Front bumper, Broken, Le - Replace and paint 735,00



Door F R, Bump(s), PDR - Knock out without painting 63,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 235,80



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

