


OPEL Zafira: 1HCD835

Vinnumber:	WOLPE9E33E2086390	Versionname:	ZAFIRA TOURER ecoFL.Cosmo S/S 136PK
First Registrationdate:	17/06/2014	Fiscalpower:	
Expertise Mileage:	88848	Power Kw:	100
Bodytype:	MPV	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2401
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			414,20
Door R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing R L, Bump(s) and scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Rear spoiler, Chemical polution, Acceptable			0,00
<i>No pictures to display</i>			
Interior, Dirty, Chemical cleaning			75,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper grille F R, Broken, E - Replace 32,40



Bonnet, Chemical polution, Acceptable 0,00

No pictures to display

Internal Boot Lining R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Broken, Le - Replace and paint 0,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display