



**RENAULT Grand Scenic: 1FCJ153**

Vinnumber:	<b>VF1JZ14P648980959</b>	Versionname:	<b>GRAND SCENIC Bose Ed.7pl.110PK</b>
First Registrationdate:	<b>23/05/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>153621</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Burgundy</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4119</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	<b>SD</b>	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/50/17/98 MS LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 5 mm</b>	Fr.R.	<b>Goodyear: 5 mm</b>
	Re.L.	<b>Goodyear: 5 mm</b>	Re.R.	<b>Goodyear: 5 mm</b>

**Assistance equipment**

Runflat	<b>No</b>
---------	-----------

Total cost ex VAT	<b>842,00</b>
-------------------	---------------

Windscreen, Scratch(es), E - Replace	<b>487,20</b>
--------------------------------------	---------------



Wing R R, Bad repair, Acceptable	<b>0,00</b>
----------------------------------	-------------



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Bump(s), LI - Repair and paint (complete) 259,80



Alloy rim R L polished, Rust, Acceptable 0,00



Door R R, Bad repair, Acceptable 0,00

