



TOYOTA AYGO: RR7748

Vinnumber:	JTDKGN00N161780	Versionname:	1.0 VVT-I X-PLAY MMT
First Registrationdate:	29/04/2016	Fiscalpower:	
Expertise Mileage:	16152	Power Kw:	51
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	4720
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

GPS storage		Luggage cover	
GPS storage	HD		
Windows electric F			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	165/60/15/77 H LightMetal			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2565,92
-------------------	---------

Bonnet, Scratch(es), LI - Repair and paint (complete)	232,06
---	--------



Wing F R, Scratch(es), LI - Repair and paint (complete)	176,14
---	--------



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Wheel cover R R, Broken, E - Replace 24,00



Door R L, Scratch(es), LI - Repair and paint (complete) 254,68



Front bumper, Scratch(es), LI - Repair and paint (complete) 169,44



Door F R, Scratch(es), LI - Repair and paint (complete) 254,68



Floor covering F L, Hole, E - Replace 240,00



Rear spoiler, Damaged, E - Replace 174,00





Roof, Scratch(es), Acceptable 0,00

No pictures to display


Door R R, Scratch(es), LI - Repair and paint (complete) 254,68



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 246,56



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Door F L, Scratch(es), LI - Repair and paint (complete) 254,68

