



SEAT LEON ST: 1KDS129

Vinnumber:	VSSZZZ5FZFR090450	Versionname:	1.6 TDI 77KW STYLE
First Registrationdate:	9/04/2015	Fiscalpower:	
Expertise Mileage:	144188	Power Kw:	77
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4305
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/94 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 2,5 mm	Fr.R.	Bridgestone: 2,5 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1533,15
-------------------	----------------

Ignition key, Missing, E - Replace	150,00
------------------------------------	---------------



Wing R L, Bump(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Tailgate, Bump(s), PDR - Knock out without painting 162,00



Door R R, Scratch(es), LI - Repair and paint (complete) 0,00



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Incomplete, E - Replace 98,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Bump(s), PDR - Knock out without painting 63,00



Interior, Stain, Cleaning 100,00





Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Door R L, Bump(s), Acceptable 0,00

No pictures to display

Wing F L, Bump(s), PDR - Knock out without painting 63,00



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Door panel F R, Burned, E - Replace 114,00



Wing R R, Bump(s), PDR - Knock out without painting 63,00

