


TOYOTA RAV4: NF6654

| | | | |
|-----------------------------------|--------------------------|--------------|------------------------------|
| Vinnnumber: | JTMYHREV70D021814 | Versionname: | RAV4 4x2 Lounge 124PK |
| First Registrationdate: | 12/09/2014 | Fiscalpower: | |
| Expertise Mileage: | 137391 | Power Kw: | 91 |
| Bodytype: | | Body color | Black |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | Front | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | OK |
| Maintenance | OK | Parking lot | 4118 |
| Battery functioning | Yes | | |
| Number of doors | 5 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|----------------------|
| Radio CD | | Central consol F |
| GPS storage | | Luggage cover |
| GPS storage | HD | Rear parking sensors |
| Windows electric F | | |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Seats F heated | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|----------------------|-------|----------------------|
| | 225/65/17/92 MS LightMetal | | | |
| Winter tyres: | Fr.L. | Pirelli: 5 mm | Fr.R. | Pirelli: 5 mm |
| | Re.L. | Pirelli: 5 mm | Re.R. | Pirelli: 5 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|-------------------------------------|---------------|
| Total cost ex VAT | 110,64 |
| Door F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R R, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Smart repair | 110,64 |



| | |
|-------------------------------|-------------|
| Wing R R, Bump(s), Acceptable | 0,00 |
|-------------------------------|-------------|

No pictures to display