



VOLVO V60: 1HBJ706			
Vinnnumber:	YV1FW73CDF1220420	Versionname:	V60 BRE D4 Kinetic Geartr.181PK Aut.
First Registrationdate:	11/06/2014	Fiscalpower:	
Expertise Mileage:	75201	Power Kw:	133
Bodytype:	Break	Body color	Beige
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	3304
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	215/50/17/95 W LightMetal			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 4 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes
Total cost ex VAT	152,00
Maintenance, Maintenance, Execute	0,00
<i>No pictures to display</i>	
Bumper R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Protection plate M, Tear, E - Replace	57,00



Bumper F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner F R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Repaired, Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	