



VOLKSWAGEN SHARAN: 1JUC638

Vinnumber:	WVWZZZ7NZFV030890	Versionname:	2.0 CR TDI 85KW COMFORTLINE BMT
First Registrationdate:	25/02/2015	Fiscalpower:	
Expertise Mileage:	126611	Power Kw:	85
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	1110
Battery functioning	Yes		
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/98 G LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1433,18
-------------------	---------

Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Tailgate, Bump(s), PDR - Knock out without painting	63,00
---	-------



Engine protective plate, Tear, E - Replace 62,00



Door F L, Unclasp(ed), N - Mount/Dismount 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 430,02



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16

