



**VOLKSWAGEN Transporter: 1HBV898**

Vinnumber:	<b>WV2ZZZ7HZFX000694</b>	Versionname:	<b>TRANSP.1200 COMBI SWB</b>
First Registrationdate:	<b>13/06/2014</b>	Fiscalpower:	<b>DSG 136PK Aut.</b>
Expertise Mileage:	<b>67652</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2121</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>9</b>		
Number head rests:	<b>9</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
GPS storage	<b>HD</b>
GPS storage	
Windows electric F	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/65/16/107 T Steel</b>			
Summer tyres:	Fr.L.	<b>Hankook: 4 mm</b>	Fr.R.	<b>Hankook: 4 mm</b>
	Re.L.	<b>Hankook: 6 mm</b>	Re.R.	<b>Hankook: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>1229,22</b>
-------------------	----------------

Rearview mirror housing R, Scratch(es), Smart repair	<b>110,64</b>
--	---------------



Tailgate, Bump(s), PDR - Knock out without painting	<b>111,00</b>
---	---------------



Door F R, Bump(s), PDR - Knock out without painting	<b>63,00</b>
---	--------------



Front bumper, Scratch(es), Smart repair 110,64



Dashboard, Hole, Acceptable 0,00



Dashboard, Hole, E - Replace 577,50



Door F L, Bump(s), PDR - Knock out without painting 82,80



Rearview mirror housing L, Scratch(es), Smart repair 110,64



Interior, Stain, Acceptable 0,00



Door R R, Bump(s), PDR - Knock out without painting 63,00

