



## VOLVO V40: HG7328

Vinnnumber:	<b>YV1MZ5150F2056846</b>	Versionname:	<b>V40 Cr.Country D3 Base Geartr.150PK Aut.</b>
First Registrationdate:	<b>17/06/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>49377</b>	Power Kw:	<b>110</b>
Bodytype:		Body color	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2314</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

## Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	<b>HD</b>	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>NOT OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>225/50/17/98 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 0 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	866,46
-------------------	--------

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	356,20
---	--------



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Interior, Dirty, Acceptable	0,00
-----------------------------	------

*No pictures to display*

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*