



VOLVO XC60: 1FFW120			
Vinnumber:	YV1DZ31A1E2509484	Versionname:	XC60 D3 Kinetic 136PK
First Registrationdate:	18/06/2013	Fiscalpower:	
Expertise Mileage:	153681	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2609
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	235/65/17/101 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm





Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes

Total cost ex VAT	943,85
Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16



Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Inner seat cover L, Damaged, E - Replace	34,60



Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror R complete, Crack, Le - Replace and paint	307,00
	
Rear window, Scratch(es), Acceptable	0,00
	
Bonnet, Chemical polution, LI - Repair and paint (complete)	348,09
	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Floor covering F L, Burned, Smart repair	0,00
	
Seat cover F L, Burned, Smart repair	0,00
