



AUDI A3: 1GMF787

Vinnnumber:	WAUZZ8V4EA149821	Versionname:	A3 SB Attraction 105PK
First Registrationdate:	10/03/2014	Fiscalpower:	
Expertise Mileage:	104183	Power Kw:	77
Bodytype:	Hatchback	Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4631
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	375,00
-------------------	---------------

Tailgate, Bad repair, Acceptable	0,00
----------------------------------	-------------





Roof, Bad repair, Acceptable	0,00
------------------------------	-------------






Bonnet, Bad repair, Acceptable 0,00






Wing F R, Scratch(es), Acceptable 0,00

No pictures to display


Roof pillar L, Bad repair, Acceptable 0,00



Roof, Hail damage, PDR - Hail 375,00




Wing R R, Bad repair, Acceptable 0,00



Door F R, Bad repair, Acceptable 0,00



Wing F R, Bad repair, Acceptable 0,00



Door R R, Bad repair, Acceptable 0,00



Door F L, Bad repair, Acceptable 0,00

