



**AUDI A3: 1GMR155**

Vinnnumber:	<b>WAUZZZ8V5EA145728</b>	Versionname:	<b>A3 SB Ambition S-tr.105PK Aut.</b>
First Registrationdate:	<b>12/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>185650</b>	Power Kw:	<b>77</b>
Bodytype:		Body color	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>3633</b>
Maintenance	<b>28700KM OF 680 DGN</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

GPS storage		Central consol F
GPS storage	<b>SD</b>	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/45/17/91 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**




Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>1132,36</b>
-------------------	----------------

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>
---	---------------

			
Bumper R, Scratch(es), LI - Repair and paint (complete)			211,80

			
Alloy rim F L, Scratch(es), Acceptable			0,00


			
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			95,00


			
Door F R, Scratch(es), Acceptable			0,00

			
Door R R, Scratch(es), Acceptable			0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)			308,20
			

Door frame R R, Bump(s) and scratch(es), It - Spot repair			115,56
			

			
Trunk lid covering R, Scratch(es), Acceptable			0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00
			