



AUDI A6: 1EPR200			
Vinnumber:	WAUZZZ4G4DN100567	Versionname:	A6 AVANT 136PK
First Registrationdate:	18/02/2013	Fiscalpower:	
Expertise Mileage:	165744	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2210
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
GPS storage	SD
GPS storage	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/60/16/91 H LightMetal			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes
Total cost ex VAT	2021,72
Wing R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Crack, E - Replace	560,64



Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16



Door F L, Bump(s), PDR - Knock out without painting 63,00



Ceiling, Stain, Cleaning 50,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Scratch(es), Acceptable 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Bumper F L, Scratch(es), It - Spot repair 115,56



Roof, Chemical polution, LI - Repair and paint (complete) 577,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

