



AUDI Q5: 1GUJ845

Vinnnumber:	WAUZZZ8R5EA093536	Versionname:	Q5 150PK
First Registrationdate:	5/05/2014	Fiscalpower:	
Expertise Mileage:	198661	Power Kw:	110
Bodytype:	SUV	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	8600 KM OU 572 JOURS	Parking lot:	4823
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/17/108 V LightMetal			
Summer tyres:	Fr.L.	Goodyear: 8 mm	Fr.R.	Goodyear: 8 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1014,20
-------------------	---------


Door F L, Bump(s), PDR - Knock out without painting	63,00
---	-------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Windscreen, Bad repair, E - Replace 560,64



Grill, Damaged, Acceptable 0,00

No pictures to display

Bumper corner R L, Scratch(es), It - Spot repair 115,56



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Sunblind L, Broken, E - Replace 180,00



Wing F R, Stone chip(s), Acceptable 0,00

No pictures to display