


AUDI A5: 1BRW270

Vinnumber:	WAUZZZ8T1BA099258	Versionname:	A5 COU Quat. Tip. 265PK
First Registrationdate:	17/08/2011	Fiscalpower:	Aut.
Expertise Mileage:	67487	Power Kw:	195
Bodytype:	Coupé	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2711
Number of doors:	3		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L
GPS storage		Seats electric F R
GPS storage	HD	Sun Roof electric
Windows electric F		Central consol F
Cruise Control		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/40/18/97 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1487,21
-------------------	----------------

Wheel hub cap F L, Missing, E - Replace	15,00
-----------------------------------------	--------------



Rearlight L, Crack, E - Replace	132,00
---------------------------------	---------------



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 441,84



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Bump(s), LI - Repair and paint (complete) 264,21



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16

