



**BMW 1: GG6217**

|                         |                          |              |                               |
|-------------------------|--------------------------|--------------|-------------------------------|
| Vinnnumber:             | <b>WBA1C11060VU95501</b> | Versionname: | <b>1 BER HATCH 118d 143PK</b> |
| First Registrationdate: | <b>6/06/2014</b>         | Fiscalpower: |                               |
| Expertise Mileage:      | <b>112224</b>            | Power Kw:    | <b>105</b>                    |
| Bodytype:               |                          | Body color:  | <b>Brown</b>                  |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                |
| Transmission:           | <b>Back</b>              | Rims summer: | <b>Aluminium</b>              |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                     |
| Maintenance:            | <b>OK</b>                | Parking lot: | <b>4702</b>                   |
| Battery functioning:    | <b>Yes</b>               |              |                               |
| Number of doors:        | <b>5</b>                 |              |                               |
| Number of seats:        | <b>5</b>                 |              |                               |
| Number head rests:      | <b>5</b>                 |              |                               |
| Rims summer:            | <b>Aluminium</b>         |              |                               |
| Category:               | <b>Passenger Car</b>     |              |                               |
| Oil level:              | <b>OK</b>                |              |                               |

**Options**

|                                |                              |                      |
|--------------------------------|------------------------------|----------------------|
| GPS storage                    |                              | Central consol F     |
| GPS storage                    | <b>HD</b>                    | Luggage cover        |
| Windows electric F             |                              | Rear parking sensors |
| Windows electric R             |                              |                      |
| Cruise Control                 |                              |                      |
| Steering wheel multifunctional |                              |                      |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |
| Type of Lining                 | <b>Lining leather</b>        |                      |
| Type of climate control        | <b>Autom climate control</b> |                      |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/55/16/91 H LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Michelin: 5 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|               | Re.L.                            | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |






**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                                       |         |
|---------------------------------------|---------|
| Total cost ex VAT                     | 1640,00 |
| Rear window, Scratch(es), E - Replace | 370,00  |



|                                   |      |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

|   |        |
|---|--------|
| Bonnet, Hail damage, PDR - Hail   | 250,00 |
|   |        |
| Roof rail R, Bump(s), E - Replace   | 95,00  |
|    |        |
| Door R R, Bump(s), Acceptable   | 0,00   |
| No pictures to display  |        |
| Alloy rim F L, Scratch(es), Acceptable  | 0,00   |
| No pictures to display  |        |
| Roof, Hail damage, PDR - Hail   | 800,00 |
|   |        |
| Roof pillar R, Hail damage, PDR - Hail  | 125,00 |
|  |        |
| Tailgate, Bad repair, Paint   | 0,00   |
|  |        |