


BMW 3: 1GMK008

Vinnumber:	WBA3D91060F406685	Versionname:	3 BER 316d 116PK
First Registrationdate:	11/03/2014	Fiscalpower:	
Expertise Mileage:	107328	Power Kw:	85
Bodytype:	Berline	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1212
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Vredestein: 8 mm	Fr.R.	Vredestein: 8 mm
	Re.L.	Vredestein: 8 mm	Re.R.	Vredestein: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	577,40
-------------------	---------------

Front bumper, Bump(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Bonnet, Bump(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Door panel F R, Damaged, Acceptable	0,00
-------------------------------------	-------------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------





No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Windscreen, Stone chip(s), Windscreen repair	58,80
	
Door F L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
<i>No pictures to display</i>	